Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight ***DHR Id#:*** **046-0032**

Resource Identification

Property Name(s): ..... Dudley House and Outbuildings {Historic}
Property Date: 1820
Address(s): ..... Route 622 {Current}
County/Independent City: Isle Of Wight
City: ... .
State, Zip: ....Virginia
USGS Quad Name: ..... RAYNOR

National Register Eligibility Status
Property is Historic (50 years or older)

Property has not been evaluated

Resource Description

Primary Resource Exterior Component Description:

Component	Comp Type/Form	Material	Material Treatment
other	other	Wood	other
Roof	Roof - Gable, front	Wood	other
Foundation	Foundation - Solid	Brick	Foundation - Not Visible
Porch	Porch - 1-story, 3-bay	Wood	other
Roof	Roof - Gable, Side	Metal	Roof - Standing Seam
Structural System	Structural System - Frame	Wood	other
Windows	Windows - Sash, double-hung	Wood	Windows - 6/6
Chimneys	Chimneys - Exterior end	Brick	Chimneys - American Bond

WUZIT Count:

No.	Wuzit Types	Historic?
1	Smoke/Meat House	Historic
1	Barn	Historic
1	Single Dwelling	Historic
1	Servant Quarters	Historic

NR Resource Count:

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* 046-0032

Individual Resource Information

WUZIT: ..... Servant Quarters

Primary Resource? ..... No
Number of Stories: 1.0
Interior Plan Type: .....
Threats to Resource: ..... Deterioration
Description: Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Smoke/Meat House

Primary Resource? ..... No
Number of Stories: 1.0
Interior Plan Type: .....
Threats to Resource: ..... Deterioration
Description: Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Barn

Primary Resource? ..... No
Number of Stories: 1.0
Interior Plan Type: .....
Threats to Resource: ..... Deterioration
Description: Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

WUZIT: ..... Single Dwelling

Est. Date of Construction: .... 1820 ca {Site Visit}
Accessed? ..... No
Primary Resource? ..... Yes
Number of Stories: 1.5
Architectural Style: ..... Other
Condition: ..... Fair
Interior Plan Type: ..... Hall Parlor
Threats to Resource: ..... Deterioration
Description: Architecture Summary: End Architecture Summary Additions and alterations: End Additions and alterations Interior Description: End Interior Description

Cemetery Information

Bridge Information

National Register Eligibility Information (Intensive Level Survey)

Historic Context(s): ..... Domestic

Bibliographic Documentation

Ownership Information

Graphic Media Documentation

Medium	*Depository ID #*	*Photo Depository*	*Date*	*File Name*
B&W 35mm Photos	969		1968/8 /99	

Cultural Resource Management (CRM) Events

Department of Historic Resources
Reconnaissance Level Survey

Isle Of Wight *DHR Id#:* **046-0032**

CRM Event # 1,
Cultural Resource Management Event: Reconnaissance Survey
Date: 973/10/99
Organization or Person: VHLC-Bernard L. Herman
CRM Event Notes or Comments:

CRM Event # 2,
Cultural Resource Management Event: Reconnaissance Survey
Date: 968/2 /14
Organization or Person: Tucker H. Hill
CRM Event Notes or Comments:

VIRGINIA
HISTORIC LANDMARKS COMMISSION
SURVEY FORM

46-32

File Number

1. County Isle of Wight
   Town
   Street No. Rt. 622

   USGS Quad Name Raynor 7.5
   Quad Date 1968
   Original Owner
   Original Use farmhouse
   Present Owner
   Present Owner Address

   Present Use abandoned

2. Historic Name
   Present Name House
   Date or Period (exact or estimate) ca. 1820
   Architect
   Builder, craftsman, etc.
   Source of Name
   Source of Date construction

3. No. stories (dormers count as ½ story): 1 1/2
   Wall construction frame
   Acreage

4. Historical Significance (Chain of Title, Families and Events, etc., connected with the property)

5. Architectural Significance (Note interesting interior and exterior details, etc., cite significant alterations and additions)

Although this small and simple house has been partially altered by the rebuilding of one of its chimney stacks and the replacement of much of the original sash, it still preserves much of its original character. Built on a hall-parlor plan this house retains several early 6 panel doors, some original sash (most notably to the right of the entrance door) and beaded weatherboard. The simplicity of the plan and detailing as well as the survival of several early features heighten the significance of this otherwise unnoticed building.

6. Physical Condition	Excellent	Good	Fair	Poor
Structure			X	
Grounds			X	
Neighborhood			X	

7. State potential threats to preservation of structure

abandoned.

(over)

8. List Number of Photographs _____Exterior _____Interior _____Outbuildings

9. Sources and Bibliography:
   A. Published Sources (author, title, date, page number, etc.)

   B. Primary Sources (original or later drawings, old photographs, pictures, manuscripts and their location)

   C. Names and Addresses of People Interviewed

10. Name, Address and Title of Recorder:

Bernard L. Herman/VHLC

Date of Record

October 1973

11. First Floor Plan (Rough Plan indicating arrangement of rooms, doorways, windows on ground floor)



12. Site Plan (Locate and identify outbuildings, dependencies, and significant farm structures)



orm 10-445
/62)

46-32

1. STATE VIRGINIA
COUNTY Isle of Wight
TOWN VICINITY Proctor's Bridge
STREET NO.

ORIGINAL OWNER
ORIGINAL USE
PRESENT OWNER Mother of Alfred T. Dudley
PRESENT USE vacant
WALL CONSTRUCTION
NO. OF STORIES

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

2. NAME Smokehouse, small barn and quarters

DATE OR PERIOD early to mid-19th C.
STYLE
ARCHITECT
BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC

Smokehouse is frame with clapboarding, one story, one door, gable roof with shingles.

Small barn is frame with clapboarding, rectangular with lean-to additions on either side of gable end front, one story.

What appears to be servant or slave quarters, part of photo is blocked out. Frame with clapboarding, rectangular (four- bay front), one story, gable roof, two entrances in center, small chimney.

5. PHYSICAL CONDITION OF STRUCTURE Endangered XX Interior Exterior

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC.

Mr. Alfred T. Dudley, history teacher at Hermitage High School

9. NAME, ADDRESS AND TITLE OF RECORDER

T. H. Hill
Architectural Historian
2/14/68
DATE OF RECORD

orm 10-445
5/62)

46-32

1. STATE VIRGINIA
COUNTY Isle of Wight
TOWN
STREET NO.
VICINITY Proctor's Bridge

ORIGINAL OWNER
ORIGINAL USE
PRESENT OWNER Mother of Alfred T. Dudley
PRESENT USE vacant
WALL CONSTRUCTION wood
NO. OF STORIES 1½

HISTORIC AMERICAN BUILDINGS SURVEY
INVENTORY

2. NAME

DATE OR PERIOD early-19th C.
STYLE
ARCHITECT
BUILDER

3. FOR LIBRARY OF CONGRESS USE

4. NOTABLE FEATURES, HISTORICAL SIGNIFICANCE AND DESCRIPTION OPEN TO PUBLIC

Frame with clapboarding, rectangular (three-bay front), 1½ stories, gable roof with three dormers in front, two exterior end chimneys, chimneys in American bond, 9/9 sash windows, rear one story ell; front bays arranged symmetrically.

5. PHYSICAL CONDITION OF STRUCTURE Endangered XX Interior Exterior fair

6. LOCATION MAP (Plan Optional)

7. PHOTOGRAPH

8. PUBLISHED SOURCES (Author, Title, Pages)
INTERVIEWS, RECORDS, PHOTOS, ETC

Mr. Alfred T. Dudley, history teacher at Hermitage High School.

9. NAME, ADDRESS AND TITLE OF RECORDER

T. H. Hill
Architectural Historian
2/14/68

DATE OF RECORD